SOLIDSOLUTIONS

SUPPORTING EXCELLENCE

KEYBOARD SHORTCUTS

WINDOWS COMMANDS

New...................................... CTRL + N
Open..................................... CTRL + O
Close File.............................. CTRL + F4
Close SOLIDWORKS .... ALT + F4
Swap Windows.......................... Ctrl + Tab
Save .... Ctrl + S
Print..................................... Ctrl + P
Find/Replace........................... Ctrl + F
Select All .... Ctrl + A
Cut .... Ctrl + X
Copy .... Ctrl + C
Paste..................................... Ctrl + V
Undo .... Ctrl + Z
Redo*.................................... Ctrl + Y

*Only works in sketches

SOLIDWORKS VIEW COMMANDS

Zoom to Fit ....F
Orientation Menu ....Spacebar
View Cube ....Ctrl + Space Bar
Front View ....Ctrl + 1
Back View ....Ctrl + 2
Left View...........................Ctrl + 3
Right View ....Ctrl + 4
Top View...........................Ctrl + 5
Bottom View ....Ctrl + 6
Isometric View...................Ctrl + 7
Normal To..........................Ctrl + 8

SOLIDWORKS COMMANDS

Recent Documents.........................R
Move Breadcrumbs to Mouse.......D
Show Shortcut Bar ....S
Repeat Last Command ....Enter
Draw Line L
Toggle between line and
arc whilst sketching ....A
Rebuild ....Ctrl + B
Forced Regeneration
(Thorough Rebuild)......................Ctrl + Q
Rebuild all configurations.............Ctrl + Shift + B
Copy Appearance ....Ctrl + Shift + C
Paste Appearance ....Ctrl + Shift + V
Search Commands..........................W
Search Help.................................H
Toggle Selection Filter Toolbar F5
Scroll to top of Feature Tree ....Home
Scroll to bottom of
Feature Tree ....End
Collapse All Tree Items.................Shift + C
Show Flat Tree..............................Ctrl + T
Show All Hidden Bodies ....Ctrl + Shift + Tab
Hide - Hover mouse over target + Tab
Show - Hover mouse over target + Shift + Tab

SOLIDWORKS